








40 G-72 1F WS



KUH.30068
KUH.40019












†8x30mm	6,4 x 50mm		†35/0mm	†5/19mm		
						
A	B	E1	HG	J		
8	8	8	2	4		
			†3.5x13mm	†3.0x20mm	†4.0x30mm	†3.0x16mm
J8	K	O				
P5	P7	P8	P11			
8	2	1	4	8-10	4	8



ISM-KUH-01151

$\pm 8 \times 30 \text{mm}$ 	$\pm 4.0 \times 30 \text{mm}$ 	
A	P8	K
8	4	2




2

6,4 x 50mm



B

4








O

1




E1

4



3




6,4 x 50mm



B

4



O






1





E1

4



4







5




6






A






C



D



7



8

FRONT

